MISCELLANEOUS ARCHITECT ENGINEER SERVICES FOR HAZARDOUS, TOXIC, AND RADIOLOGICAL WASTE (HTRW) PROJECTS FOR U.S. ARMY CORPS OF ENGINEERS WALLA WALLA DISTRICT

DRAFT REMEDIAL ACTION CLOSE-OUT REPORT

DELIVERY ORDER NO. 021

REMOVAL AND DISPOSAL OF PCB-CONTAMINATED MATERIAL HANFORD 1100-IU-I, WASHINGTON

CONTRACT NO. DACW68-94-D-0001

October 11, 1995

Prepared by:

CDM FEDERAL PROGRAMS CORPORATION 1010 Jadwin Avenue Richland, Washington 99352

Prepared for:

U.S. ARMY CORPS OF ENGINEERS
Walla Walla District
201 North 3rd Street
Walla Walla, Washington 99362



This page left intentionally blank

DRAFT REMEDIAL ACTION CLOSE-OUT REPORT

REMOVAL AND DISPOSAL OF PCB-CONTAMINATED MATERIAL HANFORD 1100-IU-1, WASHINGTON

DISTRIBUTION

No. of <u>Copies</u>

Walla Walla USACE Copie

Randy Chong 6 (5 bound, 1 unbound)

CDM Federal Programs

Paul Karas 1 (bound)
Golden Project File 1 (unbound)
Richland Project File 1 (unbound)

TABLE OF CONTENTS

<u>SE</u>	CTION		PAGE
1.0	INTRO	DUCTION	. 11
	1.1	OBJECTIVES	1 1
	1.2	SCOPE	1 1
	1.3	REPORT ORGANIZATION	1-2
2.0	SUMMA	ARY OF PREVIOUS INVESTIGATIONS	2-1
	2.1	LOCATION AND DESCRIPTION OF THE IU-1 OPERABLE UNIT	2-1
	2.2	NORTH AND SOUTH MISSILE BUNKERS	2 1
	2.3	RESULTS OF THE PREVIOUS INVESTIGATION	2-1
3.0	HYDRA	LULIC FLUID AND PCB WIPE SAMPLING	3-1
	3.1	SAMPLING OF NON-PCB-CONTAMINATED FLUID	3-1
	3.2	SUMP REMEDIATION AND PCB SAMPLING	3-2
	3.3	SAMPLING	3.2
		3.3.1 TYPES OF SAMPLES COLLECTED	3-2
		3.3.2 SAMPLE IDENTIFICATION	3_3
	3.4	ONSITE PCB WIPE-SAMPLE ANALYSIS	3-3
	3.5	OFFSITE PCB WIPE-SAMPLE ANALYSIS	3-4
4.0	HYDRA	ULIC FLUID REMOVAL AND PCB DECONTAMINATION	4-1
	4.1	SAMPLING, REMOVAL, AND DISPOSAL OF HYDRAULIC LIFT WEL	I.
		FLUIDS	. 4-1
		" THE TELL OF THE PROPERTY OF	. 4-1
	4.2	4.1.2 REMOVAL AND DISPOSITION OF HYDRAULIC FLUIDS	. 4-3
	4.2	SUMP DECONTAMINATION AND ONSITE PCB ANALYSES	. 4-3
		4.2.1 SUMP PUMP REMOVAL	. 4-4
-	•	4.2.2 NORTH BUNKER PCB DECONTAMINATION	. 4-4
		4.2.3 NORTH BUNKER PCB WIPE-SAMPLING 4.2.4 SOUTH BUNKER PCB DECONTAMINATION	. 4-4
			. 4-4
	4.3	4.2.5 SOUTH BUNKER PCB WIPE-SAMPLING	. 4-7
	بر	OFFSITE ANALYSIS OF PCB WIPE-SAMPLES	. 4-7
		4.3.1 SOUTH BUNKER CONFIRMATORY WIPE-SAMPLES	. 4-7
	4.4	4.3.2 NORTH BUNKER CONFIRMATORY WIPE-SAMPLES DISPOSITION OF DECONTAMINATION WASTES	. 4-7
- ^	OTT	•	
٥.٥	QUALII	Y ASSURANCE/QUALITY CONTROL	. 5-1
	5.1	SAMPLE ANALYSIS	. 5-1
		5.1.1 ONSITE PCB ANALYSES	. 5-1
		5.1.2 OFFSITE LABORATORIES	. 5-1

TABLE OF CONTENTS (continued)

<u>SECTION</u>		<u>PAGE</u>
•	5.1.2 OFFSITE LABORATORIES	5-1
5.2	CHEMICAL DATA QUALITY OBJECTIVES	5-1
	5.2.1 PRECISION	5-3
	5.2.2 ACCURACY	5-4
	5.2.3 SENSITIVITY	5-5
	5.2.4 COMPLETENESS	5-6
	5.2.5 COMPARABILITY	5-6
	5.2.6 REPRESENTATIVENESS	5-7
5.3	DEVIATIONS FROM FIELD PROCEDURES	5-7
5.4	USACE QA LABORATORY DATA	5-7
5.5	DATA USABILITY SUMMARY	
6.0 CONCL	USIONS	6-1
6.1	MISSILE BUNKER SUMP DECONTAMINATION	
6.2	DISPOSITION OF PCB-CONTAMINATED DECONTAMINATION	
	FLUID	6-2
7.0 REFER	ENCES	7-1
A DDENIMY	A Manifests/Rills of Lading	

iv

LIST OF FIGURES

FIGURE		
2-1	Location of the Hanford Site and the 1100 IU-1 Area	
2-2	Location of the H-52-L Missile Bunkers	2-3
2-3	Previous Sampling Locations at the North Missile Bunker Area	2-4
4-1	Screening and Confirmatory Sample Locations at the H-52-L Missile Bunkers.	4-5
	LIST OF TABLES	
TAB	BLE	PAGE
2-1	Sampling Results from Previous Investigations	2-6
4-1	Offsite Laboratory Analytical Data Summary, Hydraulic Fluid Samples	4-2
4-2	Onsite PCB Wipe-Sample Results	
4-3	Offsite Laboratory Analytical Data Summary, Confirmatory Samples	4-8
5-1	Summary of Samples Submitted for Offsite Analysis	
5-2	Deviations From Field Procedures	< 0

LIST OF ABBREVIATIONS AND ACRONYMS

ALE Arid Lands Ecology Reserve

CDM Federal CDM Federal Programs Corporation

CLP Contract Laboratory Program

CWM Chemical Waste Management, Inc.

DOE U.S. Department of Energy

EES Evergreen Environmental Services

EPA U.S. Environmental Protection Agency

ESE Environmental Science & Engineering, Inc.

ft feet, foot

gal gallon

GFAA Graphite Furnace Atomic Absorption

ICP Inductively-coupled Plasma

in. inch

MS/MSD Matrix spike/matrix spike duplicate

NPD USACE North Pacific Division Laboratory

NPL National Priorities List

OU Operable Unit

PCB polychlorinated biphenyl

PPM parts per million

QA Quality Assurance

QAPjP Quality Assurance Project Plan

QC Quality Control
%R Percent Recovery

RCRA Resource Conservation and Recovery Act

ROD Record of Decision

SAS Sound Analytical Services, Inc.

SOW Statement of Work

 $\mu g/100 \text{ cm}^2$ micrograms per one hundred square centimeters

USACE
U.S. Army Corps of Engineers, Walla Walla District

WTPH-D
Total Petroleum Hydrocarbon Analysis, Washington State Method Hydrocarbon Identification Analysis

WTPH-G
Total Petroleum Hydrocarbon Analysis, Washington State Method Gasoline Fraction

WTPH-HCID
Total Petroleum Hydrocarbon Analysis, Washington State Method --

Hydrocarbon Identification Analysis

1.0 INTRODUCTION

CDM Federal Programs Corporation (CDM Federal) has prepared this Remedial Action Close-Out Report for the U.S. Army Corps of Engineers, Walla Walla District (USACE) under Contract No. DACW68-94-D-0001. The report describes the removal and disposal of polychlorinated biphenyl (PCB)-contaminated and non-PCB-contaminated material at the Hanford 1100 Area, IU-1 Operable Unit (1100-IU-1), Hanford Reservation, Richland, Washington. Activities described in this Close-Out Report were conducted as part of the remedial action for the 1100-IU-1 portion of the 1100 Area National Priorities List (NPL) Site. This work was conducted in accordance with the USACE Statement of Work (SOW) dated April 28, 1995.

1.1 **OBJECTIVES**

The primary objective of the work described in this Close-Out Report was to decontaminate two sumps located in former missile bunkers within 1100-IU-1. These sumps were previously determined to be contaminated with PCBs. Secondly, along with decontamination of the sumps and associated sump pumps, eight auxiliary jacks were to be labeled as containing PCBs. A third objective was the sampling and removal of non-PCB-contaminated fluids from hydraulic lift wells located in the missile bunkers.

1.2 SCOPE

The scope of this project relating to the above-described objectives is as follows:

Missile Bunker Sumps – This portion of the work entailed the surface decontamination of two sumps to meet the cleanup criterion for PCB of 10 micrograms per 100 square centimeters (10 $\mu g/100 \text{ cm}^2$). Surfaces to be decontaminated were the sides and base of each sump and the exterior of the sub-floor portion of each sump pump. Successful decontamination was to be demonstrated through onsite screening and offsite analysis of wipe samples. Wastes generated during decontamination were to be characterized and appropriately disposed.

Auxiliary Jacks - Four mechanical jacks each in two missile bunker areas were to be labeled as containing PCBs based on the results of previous investigations.

Hydraulic Lift Wells – Waste fluids were to be removed from one sub-floor hydraulic lift well in each of two missile bunker areas. Fluids were to be characterized and properly disposed. Cleaning of the hydraulic lift wells was not included in this project.

2.0 SUMMARY OF PREVIOUS INVESTIGATIONS

The following section is based on the Draft Field Investigation Report for the 1100 IU-1 Operable Unit (USACE 1994a).

2.1 LOCATION AND DESCRIPTION OF THE IU-1 OPERABLE UNIT

The 1100 Area was placed on the NPL in July 1989. The 1100 Area has been divided into four OUs based on geographic area and common waste sources. The four OUs are identified as 1100-EM-1 (EM-1), 1100-EM-2 (EM-2), 1100-EM-3 (EM-3), and 1100-IU-1 (IU-1). The IU-1 OU is located approximately 20 kilometers (km) (12.5 miles [mi]) west-northwest of the city of Richland, Washington, within the Hanford Arid Lands Ecology Reserve (ALE). The location of the IU-1 OU is depicted on Figure 2-1.

2.2 NORTH AND SOUTH MISSILE BUNKERS

The H-52-L North and South Missile Bunkers lie within the IU-1 OU (Figure 2-2). Both bunkers were used as missile storage and launch facilities from approximately 1952 to 1962. The bunkers are underground facilities located near the former Nike Base headquarters that are now part of the ALE. As part of the operation of the facility, hydraulic fluids and PCBs were used.


2.3 RESULTS OF THE PREVIOUS INVESTIGATION

Equipment remaining in each bunker includes 4 auxiliary jacks, a hydraulic lift well, and a 1.2 meter (m) (4 feet [ft]) deep sump and sump pump (Figure 2-3). Each hydraulic lift well is 6 m (19 ft 10 inches [in.]) deep. The hydraulic lift wells consist of an inner and an outer casing. The inner casing is approximately 0.3 m (13 in.) in diameter, and the outer casing is approximately 0.4 m (15 in.) in diameter. The sumps are approximately 0.9 m (36 in.) in diameter. The fluid level in the North Missile Bunker lift well was approximately 5.5 m (18 1/2 ft) below the floor. The fluid level in the South Missile Bunker lift well was approximately 0.15 m (6 in.) below the floor.

PCB wipe-samples were collected from the sumps, the hydraulic lift wells, and the eight auxiliary jacks during July 15 and 16, 1994. The locations of the wipe-samples were as follows:

- The sump wipe-samples were collected from the interior walls of the sumps.
- The hydraulic lift well samples were collected from the interior of the wells.
- The auxiliary jack samples were collected from the tops of the jacks.

FACSIMILE TRANSMITTAL HEADER SHEET



CORPS OF ENGINEERS ENVIRONMENTAL ENGINEERING BRANCH

TO: Glenn Goldberg - DOE Richlan	d
VOICE NO.: (509) 376-9552	FAX NO.: (509) 376-4360
FROM: Randy Chong	
	FAX NO.: (509) 527-7811
NUMBER OF PAGES (NOT INCLU	JDING HEADER) 49
CLASSIFICATION	_ (UNCLASSIFIED IF NOT FILLED)

MESSAGE: Report on ALE Missile Bunker Remediation. Because this was outside of CERCLA (not a release to the environment) it was not a part of the 1100-IU-1 (ALE) close out report issued in 1994. However, it was agreed that the bunker would be remediated as outlined in this report. Remediation was completed in the summer of 1995. All our former Hanford Project Manager's are gone so I don't have access to (couldn't find any) files which should contain a letter transmitting this report to you. Hope this is sufficient. Give me a call if you need more info.